

It's just a
bit of hot
weather ...



In fact, hot weather can cause the overhead lines to expand and sag. To avoid damaging the lines, trains must travel more slowly than normal.



Check if your journey
is affected

nationalrail.co.uk/summer